



P4 POSITION IN CARRIAGE-MOVING CL DIRECTION (P) COUNTING AREA OF PRINT-DOT COUNTER RE ACCELERATION / DECELERATION PRINTING AREA RE RE RE 2 က <u>...</u> CONSTANT-SPEED PRINTING AREA PRINT BUFFER COUNTING AREA OF PRINT-DOT COUNTER LE <u>5</u> ACCELERATION / DECELERATION / DECELERATION HOME PRINTING AREA POSITION : Ш 4 Ш က Ш CARRIAGE SPEED Щ

FIG.

FIG. 4




FIG. 5




FIG. 6




FIG. 7





FIG. 8



en de la companya de la co





FIG. 10



٠;

FIG. 11




FIG. 12

